

# TOISA PALADIN – INSPECTION PICTURES

17 NOVEMBER 2018



## Mezzanine Deck:

Stbd side:



Port side



Main Deck view from Mezzanine

(Aft FRC Davit on port side)



Main Deck Toward Mezzanine







LSP package on Main Deck






## Sat System Layout







BELL:









SPHL


Escape trunk to port side






## Dive Plant & Machinery

### Gas Transfer Compressors






Hot Water Machine x2



Reclaim Compressor




## Lexmar Regen Units





Engine Room:

4x CAT Main Engine / Generators






Auxiliary Generator



Auxiliary with Missing / Damaged Alternator



## Main Propulsion – Azimuth





Bow Thrusters:

2x tunnel thrusters & 1x Drop Down Azimuth





